



Compatibility Summary

Ultrastar 73LZX

3.5 inch FC-AL hard disk drive



Models: IC35L009F2D210-0
IC35L018F2D210-0
IC35L036F2D210-0
IC35L073F2D210-0

Compatibility

The IBM SIT Lab thoroughly tests Ultrastar drives for compatibility with a wide variety of systems, controller cards, and operating systems. Testing was done to demonstrate general compatibility with the following hardware and software. Other combinations of hardware and software are expected to function with this drive, but have not been tested.

Systems

Dell Precision 620
Dell PowerEdge 2450
SGI Origin 200
SGI Octane
IBM pSeries 690
Sun Enterprise 450
Sun Enterprise 3500
Sun Enterprise 4500
Sun Ultra 80
Sun Blade 1000

Fibre Channel HBAs (1Gb/s)

Emulex LP8000
VMIC 5661
QLogic QLA-2100, QLA-2100/66, QLA-2200/66
Interphase 5526-E-FS-C
ATTO Express PCI FC
JNI FCE2-6410-N
Adaptec AHA-F950
Adaptec/Agilent 9110G
LSI Logic SYM40909H
HP/Agilent HHBA-5100A

Enclosures

CLARiiON FC5000
Sun StorEdge A5100/A5200
Sun StorEdge T3
Sun StorEdge MultiPack
Ciprico FibreStor 2210 JBOD/RAID
Ciprico 7000
Eurologic XL400, XL500
IBM DF4000J
IBM DF1100R
NetApp F760

Fibre Channel HBAs (2Gb/s)

Emulex LP9002, LP9002L
HP/Agilent HHBA-5220A
JNI FCE-6420D-C, FCE-6460
Adaptec AFC 9210
Interphase 5560
QLogic QLA2300

Fibre Channel Hubs/ Switches

Brocade SilkWorm 2400
Gadzoox SlingShot 4218
Vixel 7100

Operating Systems

WinNT 4.0 + SP6
Win2000 Professional + SP2
Win2000 Server + SP2
IRIX 6.5
AIX 4.3.3
Solaris 2.6, 7, 8

Notes:

1. *Every OS requires FC-AL driver modules at the appropriate level. Check OS Distribution Compatibility information before installing the drive.*
2. *Fibre Channel Host Bus Adapters require the correct level of BIOS and Firmware. Check with the manufacturer for the latest level or the correct level.*

Third Party Certification

This product has been submitted to Microsoft for certification. At the time of writing the Microsoft Master ID for the Ultrastar 73LZX has yet to be determined.



International Business Machines Corporation 2002

www.ibm.com/harddrive

IBM Technology Group Support Center

Telephone: 888.IBM.5214 or 507.286.5825

E-mail: drive@us.ibm.com

Singapore Technical Support Center

Telephone: 1800.418.9595 or 65.6.418.9595

E-mail: drive@sg.ibm.com

UK Technical Support Center

Telephone: 44.1475.898.125

E-mail: drive@uk.ibm.com

Germany Technical Support Center

Telephone: 49.7032.153050

E-mail: drive@de.ibm.com

IBM Storage Systems Division

5600 Cottle Road

San Jose, CA 95193

www.ibm.com/storage

Printed in the United States of America

01-2002

All Rights Reserved

IBM is a registered trademark and Ultrastar is a trademark of International Business Machines Corporation.

Other company, product, and service names may be trademarks or service marks of others.

Produced by the IBM Technology Group Support Center.

This information is provided for the use of OEM manufacturers and end- users attaching IBM disk drives and is believed to be accurate but is supplied without guarantee. Data subject to change without notice.

Date: 15 January 2002